

Виды насадок

- ● M5, M6, M8
- ▬ 1/8", 3/16" ● S0, S1, S2, S3
- + #0, #1, #2
- + 6, 8, 10
- ● 4, 6, 8, 10, 12
- ● T-5, T-6, T-7, T-8, T-10, T-15, T-20, T-25, T-27, T-30, T-40
- ● 2mm, 2.5mm, 3mm, 4mm, 5mm, 6mm, 8mm, 5/64", 3/32", 7/64", 1/8", 9/64", 5/32"
- ▬ C1, C2, C3
- ● 2mm x 2mm x 2mm
- ▲ 1, 2, 3, 4, 5
- + PZ0, PZ1, PZ2
- ● Трилистник